




2600 Bull Street
Columbia, SC 29201-1708

March 02, 1998

South Carolina Department of Mental Health
Attn: Mr. Hugh Grenade
Post Office Box 119
Columbia, SC 29202

Re: Stone Pavillion
2200 Harden Street
Site ID #17267
Report Received: September 29, 1997



Dear Mr. Grenade:

The Bureau of Underground Storage Tank (UST) Management of the South Carolina Department of Health and Environmental Control (SCDHEC) has reviewed the above referenced report and existing department file for the referenced site, which contained a regulated underground storage tank system. Requirements for the management of UST systems are established by the State Underground Petroleum Environmental Response Bank (SUPERB) Act and South Carolina Underground Storage Tank Control Regulations (SCUSTCR) R.61-92.

The report documents results of an environmental assessment performed during February 1997. Based on the information submitted to date, the SCDHEC does not require further site assessment or rehabilitation. However, should any contamination become evident which could be attributed to the UST system, this office can, under authority established by the SUPERB Act and SCUSTCR, require investigative and/or remedial activities.

The decision for requiring no further assessment pertains only to the referenced regulated UST system and is based solely on the information provided in the report.

This correspondence does not exempt the UST system from any additional requirements (i.e., notification, operation, release detection, corrective action, and closure) of the SCUSTCR or the SUPERB Act.

On all correspondence concerning this site, please reference the site ID number. If you have any questions or comments, feel free to call Reba Glymph-Fant at 803-734-5356.

Sincerely,

Mark Berenbrok, Manager
Regulatory Assistance Section
UST Regulatory Compliance Division
Bureau of Underground Storage Tank Management

MKB/rgf
17267/DHEC/UST/03/02/98
cc: read and file copy